

Oil Field Environmental Incident Summary

Incident: 20151029120326 **Date/Time of Notice:** 10/29/2015 12:03

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: REIGER 9-11H

Field Name: TRUAX

Well File #: 20518

Date Incident: 10/28/2015 **Time Incident:** 22:30

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 11

Qtr: SE NE

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.2	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/8/2016

Clean Up Concluded: 10/30/2015

Risk Evaluation:

None noted

Areal Extent:

The misting of crude oil covered 10 yards by 12 yards of the field to the south right off the pad.

Potential Environmental Impacts:

None noted

Action Taken or Planned:

The spill was quickly stopped and Whiting is investigating the root cause of the spill. The landowners will be notified and any impacted vegetation will most likely be mowed.

Wastes Disposal Location: Any wastes will be disposed of at an approved location.

Agencies Involved:

Updates

Date: 10/30/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to report, release impacted area off location. Further followup required.

Date: 12/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 2:54 p.m. The weather was sunny, 27°F, with wind from the southwest 0-5 mph. Currently, there is a non-vegetated pipeline right of way located on the south and west sides of the flare and treater area. I could not see any oil staining on the south side of the pad. More followup needed next summer to check on vegetation growth. 48.17277, 103.23930

Date: 8/22/2016 **Status:** Inspection

Author: Nieraeth, Shawna

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Checked on 08/16/2016. Vegetation seems to be normal. No dead spots, stunted vegetation or oil stains visually observed.